

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**



16698 U.S. PTO

041304

2/3





FIGURE 2

\* 30% Glass Filled Nylon 6  
containing 1.0% PR178 (Control) 40X Surface Photo




FIGURE 3

\* 30% Glass Filled Nylon 6  
containing 1.0% PR178 w/SEED 40X Surface Photo



FIGURE 4

SN: 09/754931  
WEBSTER

1/3


16698 U.S. PTO



041304

Control

w/Nylostab SEED



\* 30% Glass Filled Nylon 6  
containing 1.0% PR178